

# Stoughton Hospital

Project Completed: October 2013



Stoughton Hospital complex was pressure washed top to bottom - all cement, brick and stone.



Windows were squeegeed as work proceeded around building.



BEFORE: Loading Dock



AFTER: Loading Dock



BEFORE: Loading Dock



AFTER: Loading Dock



BEFORE



AFTER



BEFORE: Sprinkler Thermostate Heads (not Protected)



Protected Sprinkler Head. All sprinkler heads should be protected from particles striking thermostate and setting off sprinkler system. Without protection there can be no guarantee that glass in sprinkler head would not be struck by water pressure and break.



AFTER Sprinkler Thermostate Head



BEFORE: Emergency Room Exit



AFTER: Emergency Room Exit



BEFORE



AFTER



AFTER

BEFORE

Diminished rust stains on delicate stone surface of hospital.